

Updated as of September 14, 2021

Palomar College engaged an engineering firm to evaluate the need for additional filtration of rooms and buildings on the main campus and at the education centers. The recommendations are summarized below. If you have questions regarding your workspace, please discuss these with your supervisor.

Bldg.	Room No.	Reduced Occpncy Recommended?	Filter modifications recommended?	In-room air scrubber recommended?	Filters completed?	Scrubbers completed?
San Marcos Campus						
A	-	NO	NO	YES	N/A	YES
AA/ST	-	NO	NO	YES	N/A	YES
C	C-1	NO	NO	YES	N/A	YES
	C-2	NO	NO	YES	N/A	YES
	C-3	NO	NO	YES	N/A	YES
	C-4	NO	NO	NO	N/A	N/A
	C-7	NO	NO	YES	N/A	YES
	C-15	NO	NO	YES	N/A	YES
D	D-2	NO	NO	YES	N/A	YES
	D-6	NO	NO	YES	N/A	YES
	D-10	NO	NO	YES	N/A	YES
	D-11	NO	NO	YES	N/A	YES
	D-12	NO	NO	YES	N/A	
DA	DA-2	NO	NO	YES	N/A	YES
	DA-12	NO	NO	YES	N/A	YES
DR	-	NO	NO	YES	N/A	YES
DSPS	-	NO	NO	YES	N/A	YES
ECE	-	NO	NO	NO	N/A	N/A
F	F-2	NO	NO	YES	N/A	YES
	F-8	NO	NO	YES	N/A	YES
	F-10	NO	NO	YES	N/A	YES
	F-22	NO	NO	YES	N/A	YES
	F-24	NO	NO	YES	N/A	YES
FD	FD-1	NO	NO	YES	N/A	YES
	FD-4	NO	NO	YES	N/A	YES
G	G-3	YES	NO	YES	N/A	YES
	G-12 (Dome)	YES	NO	NO	N/A	N/A
H	H-108	NO	NO	NO	N/A	N/A
	H-217	NO	NO	NO	N/A	N/A
	H-222	NO	NO	NO	N/A	N/A
	H-310	NO	NO	NO	N/A	N/A
	H-317	NO	NO	NO	N/A	N/A
HC	-	NO	NO	NO	N/A	N/A

HS	HS-101	NO	YES	NO	YES	N/A
	HS-102	NO	YES	NO	YES	N/A
	HS-106	NO	YES	NO	YES	N/A
	HS-108	NO	YES	NO	YES	N/A
	HS-109	NO	YES	NO	YES	N/A
	HS-110	NO	YES	NO	YES	N/A
ITC	ITC-106	NO	NO	YES	N/A	YES
	ITC-110	NO	NO	YES	N/A	YES
	ITC-112	NO	NO	YES	N/A	YES
	ITC-113	YES	NO	NO	N/A	N/A
LRC	-	NO	YES	NO	YES	N/A
M	-	NO	NO	YES	N/A	YES
MC	-	NO	NO	YES	N/A	YES
MD	MD-103	NO	YES	NO	YES	N/A
	MD-119	NO	YES	NO	YES	N/A
	MD-124	NO	YES	NO	YES	N/A
	MD-133	NO	YES	NO	YES	N/A
	MD-157	NO	YES	NO	YES	N/A
	MD-205	NO	YES	NO	YES	N/A
	MD-211	NO	YES	NO	YES	N/A
	MD-223	NO	YES	NO	YES	N/A
	MD-232	NO	YES	NO	YES	N/A
	MD-305	NO	YES	NO	YES	N/A
	MD-315	NO	YES	NO	YES	N/A
	MD-328	NO	YES	NO	YES	N/A
NA	-	NO	NO	YES	N/A	YES
NB	-	NO	NO	YES	N/A	YES
NS	NS-125	NO	NO	NO	N/A	N/A
	NS-127	NO	NO	NO	N/A	N/A
	NS-131	NO	NO	NO	N/A	N/A
	NS-136	NO	YES	NO	YES	N/A
	NS-139	NO	YES	NO	YES	N/A
	NS-227	NO	NO	NO	N/A	N/A
	NS-231	NO	NO	NO	N/A	N/A
	NS-252	NO	NO	NO	N/A	N/A
	NS-333	NO	NO	NO	N/A	N/A
	NS-340	NO	NO	NO	N/A	N/A
O	O-2	YES	NO	NO	N/A	N/A
P	P-33	YES	NO	NO	N/A	N/A
PAC	PAC-110	NO	YES	NO	YES	N/A
	PAC-111	NO	YES	NO	YES	N/A
	PAC-127	NO	YES	NO	YES	N/A
	PAC-215	NO	YES	NO	YES	N/A
	PAC-216	NO	YES	NO	YES	N/A

PL	-	NO	YES	NO	YES	N/A
Q	Q-10	NO	NO	YES	N/A	YES
SSC	SSC-1	NO	NO	YES	N/A	YES
	SSC-24	NO	NO	YES	N/A	YES
	SSC-49	NO	NO	YES	N/A	YES
	SSC-35	NO	NO	YES	N/A	YES
	SSC-40	NO	NO	YES	N/A	YES
	SSC-50	NO	NO	YES	N/A	YES
SU	-	NO	NO	YES	N/A	YES
T	T-110	YES	NO	NO	N/A	N/A
	T-114	YES	NO	NO	N/A	N/A
	T-115	YES	NO	NO	N/A	N/A
	T-116	YES	NO	NO	N/A	N/A
	T-120	YES	NO	NO	N/A	N/A
	T-125	YES	NO	NO	N/A	N/A
TCA	-	NO	NO	YES	N/A	YES
TCB	-	NO	NO	YES	N/A	YES
TLC	-	NO	YES	NO	YES	N/A
WFC	-	NO	NO	YES	N/A	YES
Escondido Campus						
BUILDING 1	ESC-103	NO	NO	YES	N/A	YES
	ESC-105	NO	NO	YES	N/A	YES
	ESC-303	NO	NO	YES	N/A	YES
	ESC-304	NO	NO	YES	N/A	YES
	ESC-401	NO	NO	YES	N/A	YES
	ESC-403	NO	NO	YES	N/A	YES
	ESC-504	NO	NO	YES	N/A	YES
	ESC-505	NO	NO	YES	N/A	YES
BUILDING 2	ESC-603	NO	NO	YES	N/A	YES
	ESC-606	NO	NO	YES	N/A	YES
	ESC-700	NO	NO	YES	N/A	YES
	ESC-701	NO	NO	YES	N/A	YES
	ESC-706	NO	NO	YES	N/A	YES
BUILDING 3	ESC-805	NO	NO	YES	N/A	YES
	ESC-810	NO	NO	YES	N/A	YES
	ESC-816A	NO	NO	YES	N/A	YES
	ESC-816B	NO	NO	YES	N/A	YES
	ESC-819	NO	NO	YES	N/A	YES
	ESC-820	NO	NO	YES	N/A	YES
	ESC-821	NO	NO	YES	N/A	YES
	ESC-824	NO	NO	YES	N/A	YES
ECD BUILDING	ECD3	NO	NO	YES	N/A	YES
	ECD4	NO	NO	YES	N/A	YES

Fallbrook Campus						
BCD	-	NO	NO	NO	N/A	N/A
A	-	NO	NO	YES	N/A	YES
E	-	NO	NO	YES	N/A	YES
F	-	NO	NO	YES	N/A	YES
G	-	NO	NO	YES	N/A	YES
I	-	NO	NO	YES	N/A	YES
J	-	NO	NO	YES	N/A	YES
K	-	NO	NO	YES	N/A	YES
M	-	NO	NO	YES	N/A	YES
N	-	NO	NO	YES	N/A	YES
O	-	NO	NO	YES	N/A	YES
P	-	NO	NO	YES	N/A	YES
Q	-	NO	NO	YES	N/A	YES
Rancho Bernardo Campus						
ACs 5-7	-	NO	NO	NO	N/A	N/A
ACs 1-4	-	NO	YES	NO	YES	N/A